

# MOSAIC

PERfecta

YOUR PERFECT CHOICE IN FURNITURE

M2



EN 1021

Sanitized  
antibactérien

Martindale : 100 000

Bally Flexion : 150 000



**M389**



**M314**



**M377**



**M360**




**M330**



**M371**



**M382**




**M318**




**M310**




**M359**



**M369**



**M320**



**M350**




**M340**



**M339**

14112019

| CHARACTERISTICS   | RESULTS            | UNITS      | METHODS                         |
|---|--------------------|------------|---------------------------------|
| Total weigh   | 660+/-5%           | g/m2       | ISO 2286-2                      |
| Thickness   | 0.90-1.10          | mm         | ISO 2286-3                      |
| Coating composition   | PVC - 87           |            |                                 |
| Textile composition   | PES - 8            |            |                                 |
|   | CO - 5             |            |                                 |
| Abrasion resistance (Martindale)  | 100000 - slight    | Cycles     | ISO 5470-2                      |
| Bally Flexion   | 150000             | Cycles     | ISO 5402                        |
| Burning behaviour   | Pass               |            | <b>EN 1021-1+2</b>              |
|  | 1.IM               |            | UNI 9175                        |
|   | <b>M2</b>          |            | NF P 92-507                     |
|   |                    |            | TEST REPORT Nr LFF 2018.105     |
|   |                    |            |                                 |
| Bacterial resistance  | <b>Sanitized</b> ® |            | JIS Z 2801                      |
| Fungal resistance   | <b>Sanitized</b> ® |            | ISO 846 A                       |
| Colour fastness to rubbing (Veslic)   | 4-5                | Grey scale | DIN 54021 dry/wet - 50 cycles   |
| Colour fastness to rubbing (Crockmeter)   | 4-5                | Grey scale | ISO 105-X12 dry/wet - 20 cycles |
| Ethyl alcohol 96% vol. resistance   | 4-5                | Grey scale | DIN 54021                       |
| Light fastness  | >=6                | Blue scale | ISO 105-B02                     |

## MAINTENANCE :

Cleaning - Rub gently with a sponge or cloth moistened in a soapy water solution. Do not use multi-purpose products.

14112019



**M333**



**M391**



**M372**



**M301**



**M384**